
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-217	Smoke	8/10/2009	ADS/TM	S19KK_031MH	Dry	Yes	560.78



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-217	Smoke	8/10/2009	ADS/TM	S19KK_031MH	Dry	Yes	560.78

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19KK_024G1	S19KK_024MH	S19KK_021MH	82.5422	8
S19KK_031G1	S19KK_031MH	S19KK_024MH	170.302	8
S19KK_060G1	S19KK_060DE	S19KK_031MH	61.8491	8
S19KK_028G1	S19KK_028MH	S19KK_031MH	246.088	8

Observations & Photos

Obs_ID S1028-217-OB01 **Address** 2004 Walbrook Ave

StatusPrivateSourceCleanoutLocationYard - back

Nearest MH S19KK_031MH
Comments Smoke from cleanout in back yard. 2004

Walbrook Ave.

Picture \S1028-217-OB01-P01.jpg

Comments Back of house, 2004 Walbrook Ave.

Obs_ID S1028-217-OB02 **Address** 2008 Walbrook Ave

Status Private **Source** Cleanout

Location Yard - back **Nearest MH** S19KK_031MH

Comments Smoke from cleanout in back yard. 2008

Walbrook Ave.



Picture \S1028-217-OB02-P01.jpg

Comments Back of house, 2008 Walbrook Ave.



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary Date Ground Total Notification Company / **Test ID Inspected** Length **Test Type Blower MH** Condition Made? Super. S1028-217 8/10/2009 S19KK_031MH Yes Smoke ADS/TM Dry 560.78

Obs_ID S1028-217-OB03 **Address** 2008 Payson St

Status Private **Source** Cleanout

Location Paved concrete **Nearest MH** S19KK_031MH

Comments Smoke from cleanout in paved concrete in

back yard. 2008 Payson St.



Picture \S1028-217-OB03-P01.jpg

Comments Back of house, 2008 Payson St.